


Sparger Haul Route / use only state routes to arrive at starting point!! Make sure to obtain proper county hauling permits for hauling over-sized equipment/loads on county roads.



77179 Rankin Rd

Freeport, OH 43973

- ↑

1.

Head northwest on Rankin Rd toward Rankin Cemetery

0.8 m

↑

2.

Continue straight to stay on Rankin Rd

108 ft

↗

3.

Turn right onto Old Piedmont Rd

0.1 m

↶

4.

Turn left onto Cassville Rd

2.0 m

↶

5.

Turn left onto Pugh Rd

i

 Destination will be on the left

0.4 m
- 79101 Pugh Rd
- Freeport, OH 43973
- These directions are for planning purposes only. You may find that construction projects, traffic, weather, or other events may cause conditions to differ from the map results, and you should plan your route accordingly. You must obey all signs or notices regarding your route.

Sparger Haul Route / use only state routes to arrive at starting point!! Make sure to obtain proper county hauling permits for hauling over-sized equipment/loads on county roads.



Sparger Haul Route / use only state routes to arrive at starting point!! Make sure to obtain proper county hauling permits for hauling over-sized equipment/loads on county roads.



Sparger Haul Route / use only state routes to arrive at starting point!! Make sure to obtain proper county hauling permits for hauling over-sized equipment/loads on county roads.

