



Wilma Route - Zoom Out

Legend

- Feature 1
- Wilma Entrance
- Wilma route





Legend

- Feature 1
- Wilma Entrance
- Wilma route

Wilma Route - Zoom In




Wilma Route - 647 to CR 1

- Legend
- Feature 1
 - Wilma Entrance
 - Wilma route

Wilma Route - 647 to CR 1
Street View


- Legend
- Feature 1
 - Wilma Entrance
 - Wilma route



Wilma Route - end of route, CR 1

- Legend
- Feature 1
 - Wilma Entrance
 - Wilma route

Wilma Entrance





Wilma Haul Route: Turn by Turn

From the North/West (Cadiz):

From Cadiz, take US 250 East for 12.3 miles to the 250 & 150 split (or Y)
Veer Left onto SR 150 East and continue for 3.76 miles to Mount Pleasant
In Mount Pleasant, stay straight at the SR 150 & 647 intersection
Continue on SR 647 for 0.5 miles and turn Left/East onto County Road 1A
Continue on County Road 1A for 2.3 miles to well site entrance. Please note:
Approximately 1.8 miles after turning onto County Road 1A, the road will split.
Veer right to stay on County Road 1A

From the South (Bridgeport):

Take US 250 West for 12.3 miles to the 250 & 150 split (or Y)
Sharp Right/East onto SR 150 East and continue for 3.76 miles to Mount Pleasant
In Mount Pleasant, stay straight at the SR 150 & 647 intersection
Continue on SR 647 for 0.5 miles and turn Left/East onto County Road 1A
Continue on County Road 1A for 2.3 miles to well site entrance. Please note:
Approximately 1.8 miles after turning onto County Road 1A, the road will split.
Veer right to stay on County Road 1A

It is advisable to keep the attached RUMA either in all vehicles or accessible by mobile device. All oversized/overloaded vehicles will need a permit through the ODOT website. Any route applied for with ODOT that can't be navigated will kick back with an alternate route. Please contact ARU's Field Superintendent, Jeff Beck, at 614-896-0599 or jeff.beck@ascentresources.com prior to using the route. Even though ODOT approves, it still could include unauthorized roads/bridges.